


FAG FEELER-GAUGE-100参数

| | | | |
|----|-----|----|--|
| 说明 | 100 | mm | 塞尺长度 单位为mm的塞尺厚度: 0,03 0,04 0,05 0,06 0,07 0,08 0,09 0,10 0,12 0,14 0,16 0,18 0,20 |
|----|-----|----|--|

FAG FEELER-GAUGE-100图片



参考资料:<http://www.sozhou.com/p/201712cd.html>