

### FAG HS71907-C-T-P4S参数

|        |            |       |       |             |
|--------|------------|-------|-------|-------------|
| 尺寸     | d          | 35    | mm    | -           |
|        | D          | 55    | mm    | -           |
|        | B          | 10    | mm    | -           |
|        | a          | 11    | mm    | -           |
|        | $D_a$ H12  | 48.5  | mm    | -           |
|        | $d_a$ h12  | 41    | mm    | -           |
|        | $r_a$ max  | 0.6   | mm    | -           |
|        | $r_{min}$  | 0.6   | mm    | -           |
|        | 重量         | m     | 81    | g           |
| 基本额定载荷 | $C_r$      | 6400  | N     | 基本额定动载荷，径向  |
|        | $C_{0r}$   | 3800  | N     | 基本额定静载荷，径向  |
| 极限转速   | $n_G$ Fett | 36000 | r/min | 脂润滑时的极限转速   |
|        | $n_G$ Öl   | 56000 | r/min | 最少油润滑时的极限转速 |
| 疲劳极限载荷 | $C_{ur}$   | 390   | N     | 疲劳极限载荷，径向   |

### FAG HS71907-C-T-P4S图片



