

### FAG 31328-X-N11CA参数

|          |                 |         |         |             |             |
|----------|-----------------|---------|---------|-------------|-------------|
| 尺寸       | d               | 140     | mm      | -           |             |
|          | D               | 300     | mm      | -           |             |
|          | 2T              | 154     | mm      | -           |             |
|          | 2B              | 140     | mm      | -           |             |
|          | A               | 60      | mm      | -           |             |
|          | $C_{a \min}$    | 9       | mm      | -           |             |
|          | $D_{a \max}$    | 282     | mm      | -           |             |
|          | $D_{a \min}$    | 235     | mm      | -           |             |
|          | $d_{a \max}$    | 169     | mm      | -           |             |
|          | $r_{3, 4 \min}$ | 4       | mm      | -           |             |
|          | $r_{b \max}$    | 4       | mm      | -           |             |
|          | 重量              | m       | 45600   | g           | 质量          |
|          | 基本额定载荷          | $C_r$   | 1200000 | N           | 基本额定动载荷, 径向 |
| $C_{0r}$ |                 | 1810000 | N       | 基本额定静载荷, 径向 |             |
| 计算系数     | e               | 0.83    |         | -           |             |
|          | $Y_0$           | 0.8     |         | -           |             |
|          | $Y_1$           | 0.82    |         | -           |             |
|          | $Y_2$           | 1.22    |         | -           |             |
| 疲劳极限载荷   | $C_{ur}$        | 205000  | N       | 疲劳极限载荷, 径向  |             |
| 极限转速     | $n_G$           | 2350    | r/min   | 极限转速        |             |
| 参考转速     | $n_B$           | 1720    | r/min   | 参考速度        |             |

### FAG 31328-X-N11CA图片





参考资料:<http://www.sozhou.com/p/90d6984b.html>